Site number:

Address101/103/105 cor. Marcy St. (99-113)

New tax map(1979) U4 lot 3&4 size 40,562sq.
Old tax map 9 lot 93 size ft.

Owner SAWTELLE, JOSEPH Address 583 Circuit Rd.

Location of legal description: Rockingham County Registry of Deeds Hampton Road; Exeter, New Hampshire 03833

Representation in existing surveys: HABS NR NHL

HAER_ Other

Date c. 1850

Source:Estimate x

Other:

On 1850 map.

Historic name Common name Original owner Architect/bldr.

Functional type rowhouse
Present use, if different vacant

Moved Altered

Date Date

Effect: Focal non-contributing

Contributing X
Intrusion

Photo roll 9 no. 16
Negative with: Portsmouth Advocates
Description
Date taken by

Vernacular Greek

1.Style Revival No. of stories 22

No. of bays 8 x 2 (right side)

2. Overall plan: Long rectangle, along street.

3.Foundation: Brick Stone x Poured concrete Concrete block Artificial stone Other

4.Wall structure:Woodframe__ Brick_x Stone__ Other__ If wood: Post and beam_x Balloon frame.__ roof

5.Wall covering: Clapboard Wood shingle Flushboard Imitation ashlar Brick x Stone Stucco Composition board Aluminum Vinyl Sheet metal Asphalt shingles Other

6.Roof: Gablex Hip Shed Mansard Flat Gambrel Other

7. Specific features (location, no., appearance of porches, windows, doors, chimnies, dormers, ells/wings--see also description), decorative elements: No windows left side except one in attic. Boxed cornice. Doors in second, fourth, sixth, eight bays. Only seven windows in second story of facade.

8. Outbuildings:

PORTSMOUTH ADVOCATES, INC.

Description:

A $2\frac{1}{2}$ story, gable roofed brick rowhouse block of three units dating from the mid-nineteenth century. Boxed cornice. Segmentally arched window heads (brick), granite sills. Although the window sash is in the process of being replaced by 6/6 sash, some remaining 2/2 may represent the original. Doors in second, fourth, sixth and eight bays, all arcuated except for the one in the fourth bay, which has a rectangular granite lintel. Cut granite foundation. Iron tie rod fastenings visible at line of division between stories. Shutters indicated by some surviving shutter hooks, two chimneys on rear slope of roof, between units. Rear wall shows flashing and tar remaining from one story gable roofed sheds over each door.

